

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Case Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1507	12 Cathedral Pl, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	PR2021-2005	128 Whispering Brook Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	PR2021-2005	128 Whispering Brook Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Building Final	Failed
<input type="checkbox"/>	PR2021-0144	131 Marine St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Lath	Failed
<input type="checkbox"/>	BP2022-1708	16 Florida Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Shed Final	Passed
<input type="checkbox"/>	BP2022-0982	163 School St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2022-0982	163 School St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Complete Rough	Partial Pass
<input type="checkbox"/>	BP2022-1737	166 Marine St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1643	212 Alcazar St, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Complete Rough	Failed
<input type="checkbox"/>	PR2021-2049	212 WHISPERING BROOK DR		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-0341	24 Coquina Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2022-0341	24 Coquina Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2022-0823	247 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	BP2022-1803	26 Beacon St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1652	325 Saint George St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-0544	367 Five Island Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0030	40 Water St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	PR2021-2129	45 Coquina Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2022-1194	51 Menendez Rd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2022-0752	58 Hypolita St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Passed

<input type="checkbox"/>	Case Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0752	58 Hypolita St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-0752	58 Hypolita St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0752	58 Hypolita St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1695	61 San Marco Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-1127	78 Amarante Ln, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-1127	78 Amarante Ln, Saint Augustine, Florida, 32095	rhurry@staug-ms01	Complete Rough	Passed