

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Contractors	Reports	Project Manager	Assets	GIS		
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1763	14 Rollins Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2022-1205	149 Pasarela Dr, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1702	172 San Marco Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Failed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Mechanical Rough	Failed
<input type="checkbox"/>	BP2022-0095	18 Beacon St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2022-1028	23 Spencer St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-1028	23 Spencer St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Siding	Passed
<input type="checkbox"/>	BP2022-1114	26 Beacon St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Fill Cell / Lintel	Passed
<input type="checkbox"/>	PR2021-1795	31 Cortez Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Lath	Failed
<input type="checkbox"/>	BP2022-1496	32 Avenida Menendez, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-1806	331 Saint George St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	PR2021-1999	44 E Park Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Failed
<input type="checkbox"/>	BP2022-1526	60 Comares Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1526	60 Comares Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Final	Passed
<input type="checkbox"/>	PR2021-1311	700 Flagler Crossing Dr, Saint Augustine, Florida, 32084		privateprovider	Window / Door	
<input type="checkbox"/>	BP2022-1127	78 Amarante Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-0699	906 Anastasia Blvd, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Plumbing Final	Passed

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0699	906 Anastasia Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-0699	906 Anastasia Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2022-0699	906 Anastasia Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Building Final	Failed