

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0597	115 Bridge St, Saint Augustine, Florida, 32084	privateprovider	Deck, Bond & Lights	
<input type="checkbox"/>	BP2023-0929	120 Arredondo Ave, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0179	15 Pacific St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Insulation	Failed
<input type="checkbox"/>	BP2022-1389	170 Pasarela Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Blower Door Test	Passed
<input type="checkbox"/>	BP2023-0351	24 River Rd, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-0352	26 River Rd, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1769	26 Sebastian Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Pool Final / Alarm	Passed
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080	privateprovider	Wall Sheeting	
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080	privateprovider	Roof Sheeting	
<input type="checkbox"/>	BP2023-0764	33 Comares Ave, Unit 302, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-0764	33 Comares Ave, Unit 302, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-0764	33 Comares Ave, Unit 302, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-0764	33 Comares Ave, Unit 302, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-2097	38 Dufferin St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Pool Final / Alarm	Failed
<input type="checkbox"/>	BP2023-1067	3874 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2020-1673	5 Prawn St, Saint Augustine, Florida, 32084	privateprovider	Insulation	Partial Pass
<input type="checkbox"/>	PR2020-1673	5 Prawn St, Saint Augustine, Florida, 32084	privateprovider	Frame	
<input type="checkbox"/>	BP2023-0186	66 Spring St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	PR2021-1308	725 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Early Power	Passed
<input type="checkbox"/>	BP2023-0780	73 Park Pl, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof Final	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	<u>BP2022-0802</u>	95 Dolphin Dr, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	<u>BP2022-1407</u>	97 Anderson St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Blower Door Test	Failed