

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0414	100 Amarante Ln, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0992	1050 Bella Vista Blvd, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Failed
<input type="checkbox"/>	BP2023-0312	113 Lincoln St, Saint Augustine, Florida, 32084		cboles@staug-ms01	Fence Final	Passed
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1633	130 Shipyard Way, Saint Augustine, Florida, 32084		privateprovider	Rough Plumbing	
<input type="checkbox"/>	BP2023-1213	164 Gault St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-1146	201 Arpieka Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-0902	204 Inlet Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2023-0599	214 Pelican Reef Dr, Saint Augustine, Florida, 32080		privateprovider	Early Power	Passed
<input type="checkbox"/>	BP2022-1258	259 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1258	259 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2023-0833	27 Magnolia Dr, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Failed
<input type="checkbox"/>	BP2023-0329	3531 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0329	3531 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2023-0329	3531 N Ponce de Leon Blvd, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1599	50 Marine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Rough Plumbing	Partial Pass
<input type="checkbox"/>	BP2023-0814	6 Coleman Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1182	9 May St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Final	Failed

Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display	
<input type="checkbox"/>	BP2023-0953	92 Pescado Dr, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-0422	955 Fish Island Pl, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Electrical Final	Passed