

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0168	115 Bridge St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2022-1562	135 Theodore St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Wall Sheeting	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-2057	159 Lamego Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2023-1063	168 Twine St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1235	180 Tesoro Ter, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Steel, Bond & Pressure	Failed
<input type="checkbox"/>	BP2023-0599	214 Pelican Reef Dr, Saint Augustine, Florida, 32080		privateprovider	Window / Door	
<input type="checkbox"/>	BP2023-0428	24 Atlantic Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Deck, Bond & Lights	Failed
<input type="checkbox"/>	PR2021-1795	31 Cortez Ave, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1238	33 Casanova Rd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Dry Wall	Passed
<input type="checkbox"/>	BP2023-0184	36 Granada St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Footings	Partial Pass
<input type="checkbox"/>	BP2023-0425	40 1/2 Carrera St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0621	438 Arricola Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-0923	55 Amarante Ln, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-1259	66 Colon Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-1259	66 Colon Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2023-1259	66 Colon Ave, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-0906	74 Fullerwood Dr, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Final	Partial Pass
<input type="checkbox"/>	BP2022-1899	81 Lincoln St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Footings	Failed
<input type="checkbox"/>	BP2023-1365	84 Water St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-1272	961 Lew Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Mechanical Final	Passed