

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-1493	119 Gaillardia Loop, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1211	131 Marine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2023-1392	16 Spencer St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1170	2 Eugene Pl, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Final	Failed
<input type="checkbox"/>	BP2023-0458	208 Alcazar St, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Service Change	Failed
<input type="checkbox"/>	BP2023-1297	208 Alcazar St, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-0599	214 Pelican Reef Dr, Saint Augustine, Florida, 32080		privateprovider	Insulation	Passed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Gas Rough & Pressure	Passed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Electrical Cover	Partial Pass
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Frame	Partial Pass
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1597	265 E Marina Cove Dr, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0152	268 S Matanzas Blvd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Pool Final / Alarm	Failed
<input type="checkbox"/>	BP2023-1374	27 Sevilla St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	PR2021-1637	281 San Marco Ave, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Lath	Passed
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080		privateprovider	Fire Wall	Failed
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080		privateprovider	Top Out	Passed
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080		privateprovider	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0912	307 Arricola Ave, Saint Augustine, Florida, 32080		privateprovider	Electrical Cover	Failed
<input type="checkbox"/>	BP2023-0231	35 Miruela Ave, Saint Augustine, Florida, 32080		rhurry@staug-ms01	Gas Final	Failed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1274	41 Rohde Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-1372	56 S Whitney St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	PR2021-1310	733 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Slab	Passed
<input type="checkbox"/>	BP2022-2081	74 King St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Building Final	Partial Pass
<input type="checkbox"/>	BP2023-0818	77 Bridge St, Saint Augustine, Florida, 32084	cboles@staug-ms01	Final	
<input type="checkbox"/>	BP2023-1197	79 N Saint Augustine Blvd, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-1327	82 Water St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Gas Rough & Pressure	Failed
<input type="checkbox"/>	BP2023-1267	93 Kings Ferry Way, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed