

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-2084	10 First St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0914	103 Palmer St, Saint Augustine, Florida, 32084		privateprovider	Early Power	Passed
<input type="checkbox"/>	BP2023-0937	110 Palmer St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-1033	111 Colon Ave, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1824	112 Palmer St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2023-1527	125 Palmer St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2022-0696	14 Court Theophelia, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-0696	14 Court Theophelia, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Final	Passed
<input type="checkbox"/>	BP2023-1050	15 Pine St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Roof In Progress	Failed
<input type="checkbox"/>	BP2023-1508	16 Saragossa St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1163	180 Tesoro Ter, Saint Augustine, Florida, 32095		rschauland@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-1595	2 Sanchez Cv, Saint Augustine, Florida, 32080		rschauland@staug-ms01	Dry Wall	Failed
<input type="checkbox"/>	BP2023-0305	211 Lamego Ln, Saint Augustine, Florida, 32095		rschauland@staug-ms01	Pool Final / Alarm	Passed
<input type="checkbox"/>	BP2023-1442	258 Spring St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-1318	26 Rio Vista Dr, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2023-1561	312 Saint George St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2023-0148	32 San Marco Ave, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Demo	Passed
<input type="checkbox"/>	BP2022-1855	32 San Marco Ave, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-1053	41 1/2 Madeore St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1053	41 1/2 Madeore St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Electrical Cover	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1053	41 1/2 Madeore St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-1555	41 Coquina Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-0918	48 Phillips St, Saint Augustine, Florida, 32084	privateprovider	Rough Plumbing	Passed
<input type="checkbox"/>	BP2022-2079	49 Valencia St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Insulation	Partial Pass
<input type="checkbox"/>	BP2023-1506	5 Rollins Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1094	53 Carrera St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Dry In	Failed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Frame	Partial Pass
<input type="checkbox"/>	BP2023-0360	595 Pantano Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2023-1524	65 Saragossa St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2023-1344	68 Comares Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Window / Door	Passed
<input type="checkbox"/>	BP2023-1344	68 Comares Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2023-1344	68 Comares Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-1530	7 Nesmith Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	PR2021-1310	711 Flagler Crossing Dr, Saint Augustine, Florida, 32084	privateprovider	Frame	
<input type="checkbox"/>	BP2023-1349	78 Pajaro Way, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-1463	90 M L King Ave, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Roof Sheeting	Passed
<input type="checkbox"/>	BP2023-1227	917 Lew Blvd, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-1449	97 Coquina Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-1448	99 Coquina Ave, Saint Augustine, Florida, 32080	rschauland@staug-ms01	Footings	Passed
<input type="checkbox"/>	BP2023-1116	Drury Ln, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Roof Final	Passed