

Search...

Schauland, Richard "Buddy" ▾

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1243	1000 Harbour Vista Cir, Bldg. 39, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2023-1243	1000 Harbour Vista Cir, Bldg. 39, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0914	103 Palmer St, Saint Augustine, Florida, 32084		privateprovider	Insulation	
<input type="checkbox"/>	BP2023-1318	26 Rio Vista Dr, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2022-2001	29 Masters Dr, Saint Augustine, Florida, 32084		privateprovider	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-2001	29 Masters Dr, Saint Augustine, Florida, 32084		privateprovider	Frame	Failed
<input type="checkbox"/>	BP2022-2001	29 Masters Dr, Saint Augustine, Florida, 32084		privateprovider	Electrical Cover	Failed
<input type="checkbox"/>	BP2022-2001	29 Masters Dr, Saint Augustine, Florida, 32084		privateprovider	Early Power	Not Ready
<input type="checkbox"/>	BP2023-1231	2A Sanchez Cv, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Steel, Bond & Pressure	Passed
<input type="checkbox"/>	BP2023-1354	318 Arricola Ave, Apt 102, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-1354	318 Arricola Ave, Apt 102, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1355	318 Arricola Ave, Apt 104, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-1355	318 Arricola Ave, Apt 104, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1587	46 Charlotte St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Dry In	Passed
<input type="checkbox"/>	BP2022-0940	57 Oneida St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Frame	Partial Pass
<input type="checkbox"/>	BP2023-1514	75 Cedar St, Saint Augustine, Florida, 32084		smatthews@staug-ms01	Roof In Progress	Passed