

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan

Drag a column header and drop it here to group by that column

<input type="checkbox"/>	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-1150	1 Park Terrace Dr, Saint Augustine, Florida, 32080	rvanmierop@staug-ms01	Fence Final	Passed
<input type="checkbox"/>	BP2022-0701	11 Magnolia Ave, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Building Final	Not Ready
<input type="checkbox"/>	BP2022-1366	11 Poinciana Cove Rd, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2023-0937	110 Palmer St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2023-0937	110 Palmer St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0937	110 Palmer St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Cover	Passed
<input type="checkbox"/>	BP2022-1901	13 Pine St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	Partial Pass
<input type="checkbox"/>	BP2023-1071	16 Aviles Dr, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-1090	21 Water St, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-0750	22 Grove Ave, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-1137	24 Beacon St, Saint Augustine, Florida, 32084	cboles@staug-ms01	Fence Final	Passed
<input type="checkbox"/>	BP2023-0787	246 Pescado Dr, Saint Augustine, Florida, 32095	smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2023-1011	284 W King St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-1542	3 Hildreth Dr, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Roof In Progress	Passed
<input type="checkbox"/>	BP2023-1356	318 Arricola Ave, Apt 204, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Rough Plumbing	Passed
<input type="checkbox"/>	BP2023-1356	318 Arricola Ave, Apt 204, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2023-0764	33 Comares Ave, Unit 302, Saint Augustine, Florida, 32080	rhurry@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2023-1619	3302 Haley Pointe Rd, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1591	4000 Grande Vista Blvd, Saint Augustine, Florida, 32084	smatthews@staug-ms01	Window / Door	
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Blower Door Test	Passed

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095	rschauland@staug-ms01	Elevation Certificate	Passed
<input type="checkbox"/>	BP2023-1338	Harbour Vista Cir, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof Final	Passed
<input type="checkbox"/>	BP2023-1347	Harbour Vista Cir, Saint Augustine, Florida, 32080	smatthews@staug-ms01	Roof In Progress	Passed