

Inbox	New Service Request	New Work Order	New Inspection	New Case	Task Manager	Designer
PLL Admin	PLL Contractors	Reports	Project Manager	Assets	GIS	DigEplan
Drag a column header and drop it here to group by that column						
<input type="checkbox"/>	Number	Location		Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0392	10 Mc Millan St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Early Power	Passed
<input type="checkbox"/>	BP2023-1563	110 Portada Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	PR2021-1424	112 Moore St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2023-1629	112 Riberia St, Saint Augustine, Florida, 32084		rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0929	120 Arredondo Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2023-0929	120 Arredondo Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2023-0929	120 Arredondo Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Building Final	Passed
<input type="checkbox"/>	BP2022-1901	13 Pine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Top Out	Passed
<input type="checkbox"/>	BP2022-1901	13 Pine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Mechanical Rough	Passed
<input type="checkbox"/>	BP2022-1901	13 Pine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Electrical Cover	Failed
<input type="checkbox"/>	BP2022-1901	13 Pine St, Saint Augustine, Florida, 32084		rhurry@staug-ms01	Frame	Passed
<input type="checkbox"/>	BP2022-0291	27 Casanova Rd, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Gas Final	Passed
<input type="checkbox"/>	BP2023-1040	381 Tesoro Ter, Saint Augustine, Florida, 32095		smatthews@staug-ms01	Insulation	Passed
<input type="checkbox"/>	BP2023-0918	48 Phillips St, Saint Augustine, Florida, 32084		privateprovider	Slab	Passed
<input type="checkbox"/>	BP2023-1232	519 Arricola Ave, Saint Augustine, Florida, 32080		smatthews@staug-ms01	Deck, Bond & Lights	Passed
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Mechanical Final	Failed
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Electrical Final	Passed
<input type="checkbox"/>	BP2022-0907	565 Pantano Dr, Saint Augustine, Florida, 32095		rhurry@staug-ms01	Building Final	Failed
<input type="checkbox"/>	BP2023-0736	700 Anastasia Blvd, Saint Augustine, Florida, 32080		privateprovider	Frame	

	Number	Location	Task - Assigned To	Task - Task Description	Task - Result Display
<input type="checkbox"/>	BP2023-0736	700 Anastasia Blvd, Saint Augustine, Florida, 32080	privateprovider	Electrical Cover	
<input type="checkbox"/>	BP2023-0736	700 Anastasia Blvd, Saint Augustine, Florida, 32080	privateprovider	Top Out	Partial Pass
<input type="checkbox"/>	BP2022-1600	89 Saint Francis St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Electrical Final	Failed
<input type="checkbox"/>	BP2022-1600	89 Saint Francis St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Mechanical Final	Passed
<input type="checkbox"/>	BP2022-1600	89 Saint Francis St, Saint Augustine, Florida, 32084	rschauland@staug-ms01	Plumbing Final	Passed
<input type="checkbox"/>	BP2022-1600	89 Saint Francis St, Saint Augustine, Florida, 32084	rhurry@staug-ms01	Building Final	Failed